

REPORT OF CHANNEL CONDITIONS (FOR CHANNELS 400 FEET WIDE OR GREATER) <i>(EP 1130-2-520)</i>						PAGE 1 OF PAGES 1 DATE 23 July 2008		
TO: Navigation Interest					FROM: U.S. Army Engineer District, Baltimore P.O. Box 1715 Baltimore, Maryland 21203-1715			
RIVER/HARBOR NAME AND STATE Baltimore Harbor Baltimore, Maryland					MINIMUM DEPTHS IN EACH 1/4 WIDTH OF CHANNEL ENTERING FROM SEAWARD			
NAME OF CHANNEL	DATE OF SURVEY	AUTHORIZED PROJECT			LEFT OUTSIDE QUARTER (feet)	MID-CHANNEL		
		WIDTH (feet)	LENGTH (miles)	DEPTH (feet)		LEFT INSIDE QUARTER (feet)	RIGHT INSIDE QUARTER (feet)	RIGHT OUTSIDE QUARTER (feet)
Brewerton Channel Eastern Extension Station 0+000 to 33+600	15 May 2008	600	6	35	33	36	36	32
REMARKS <i>(Continue on reverse)</i> All depths refer to MLLW for the 1983-2001 tidal epoch. This information represents the results of surveys made on the dates shown and can only be as indicating the general conditions at that time. Actual length of channel is 6.36 miles. LQ=E1475403.31, N549645.72 (32.9') LIQ=E1487420.05, N545221.66 (35.6) RIQ=E1503604.40, N539390.33 (35.7) RQ=E1479067.24, N548873.99 (32.1)								